

Change Notice

FB & SB Series

Changes to Location & Production for FB & SB4011 Pushbuttons

Type of Change:

- Engineering Part Number
 Product Appearance



Changes for FB & SB Pushbuttons

I. The location of production will change for FB and SB4011 Pushbuttons from the Japan factory to the Philippines factory. The place of manufacture will no longer appear on the switches. The lot number on the switch case will have a dot mark above the second digit, and the box in which the switches are packaged for shipping will read "PHILIPPINES FACTORY" instead of "JAPAN FACTORY." All of these revisions will apply to standard, custom and UL/CSA approved products. Effected standard part numbers for FB are below, and those for SB are on the following page.

	Switch Case	Lot Number	Shipping Box
Before Changes	"JAPAN" on Switch Case	Example of Lot Number 79	 "JAPAN FACTORY" printed on side of box
After Changes	"JAPAN" on Switch Case Removed	Example of Lot Number with Dot Mark Above Second Digit 7[•]9	 "PHILIPPINES FACTORY" printed on side of box

Notes

There are no changes to the switches' dimensions or specifications.
The location of the lot number on switch case may vary depending on the part number.
Contact the factory if more details are needed.

Change 1: FB Part Numbers Effected by Revisions					
FB15ANEP2-FA	FB15ANEP2-HB	FB15ANEP4-FC	FB15ANP2-FA	FB15ANP2-HB	FB15ANP4-FC
FB15ANEP2-FB	FB15ANEP2-HC	FB15ANEP4-HA	FB15ANP2-FB	FB15ANP2-HC	FB15ANP4-HA
FB15ANEP2-FC	FB15ANEP4-FA	FB15ANEP4-HB	FB15ANP2-FC	FB15ANP4-FA	FB15ANP4-HB
FB15ANEP2-HA	FB15ANEP4-FB	FB15ANEP4-HC	FB15ANP2-HA	FB15ANP4-FB	FB15ANP4-HC

Effective Date

Production changes for FB and SB Series Pushbuttons will be effective May 2018.

NKK SWITCHES CO., LTD. <http://www.nkk.com> E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031

Change Notice

FB & SB Series

*** Changes 1 & 2: SB Part Numbers Effected by Revisions**

SB4011NOM	SB4011NOMCG	SB4011NOHC	SB4011NCMG	SB4011NCH	SB4011NCHCG
SB4011NOMG	SB4011NOH	SB4011NOHCG	SB4011NCMC	SB4011NCHG	—
SB4011NOMC	SB4011NOHG	SB4011NCM	SB4011NCMCG	SB4011NCHC	—

* Includes all cap color codes 2A, 2B, 2C, 2E, 2F, 2G

Change to Logo for SB4011 Pushbuttons

Type of Change:

- Engineering Part Number
 Product Appearance

2. SB4011 Pushbuttons will have an update to the NKK logo, as illustrated on the following table. The change applies to standard, custom and UL/CSA approved products. Effected standard part numbers are on the table above.

Before Change		Logo Update		After Change	
Older NKK Logo		NKK Logo Updated			

UL Factory Code Added for FB & SB4011 Pushbuttons

Type of Change:

- Engineering Part Number
 Product Appearance

3. FB and SB4011 Pushbuttons with UL approval will have a change on the switch case to include both standard and custom devices. Previously, the UL symbol appeared on the case without a factory code. After the change, the code 080 will appear next to the UL symbol, as shown here. Effected standard part numbers are on the following page.

Before Change		UL Factory Code Change		After Change	
UL Approval & No Factory Code		UL Approval & Factory Code Added			

Notes (Apply to Changes 2 & 3)

There are no changes to the switches' dimensions or specifications.
 The location of logo or UL code on switch case may vary depending on the part number.
 Contact the factory if more details are needed.

Effective Date

The logo and UL factory code changes for FB and SB Series Pushbuttons will be effective May 2018.

NKK SWITCHES CO., LTD. <http://www.nkk.com> E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031

Change Notice

FB & SB Series

Change 3: FB Part Numbers Effected by Revisions

FB15ANEP2/U-FA	FB15ANEP2/U-HB	FB15ANEP4/U-FC	FB15ANP2/U-FA	FB15ANP2/U-HB	FB15ANP4/U-FC
FB15ANEP2/U-FB	FB15ANEP2/U-HC	FB15ANEP4/U-HA	FB15ANP2/U-FB	FB15ANP2/U-HC	FB15ANP4/U-HA
FB15ANEP2/U-FC	FB15ANEP4/U-FA	FB15ANEP4/U-HB	FB15ANP2/U-FC	FB15ANP4/U-FA	FB15ANP4/U-HB
FB15ANEP2/U-HA	FB15ANEP4/U-FB	FB15ANEP4/U-HC	FB15ANP2/U-HA	FB15ANP4/U-FB	FB15ANP4/U-HC

*** Change 3: SB Part Numbers Effected by Revisions**

SB4011NOM/U	SB4011NOMCG/U	SB4011NOHC/U	SB4011NCMG/U	SB4011NCH/U	SB4011NCHCG/U
SB4011NOMG/U	SB4011NOH/U	SB4011NOHCG/U	SB4011NCMC/U	SB4011NCHG/U	—
SB4011NOMC/U	SB4011NOHG/U	SB4011NCM/U	SB4011NCMCG/U	SB4011NCHC/U	—

* Includes all cap color codes 2A, 2B, 2C, 2E, 2F, 2G

Effective Date

The logo and UL factory code changes for FB and SB Series Pushbuttons will be effective May 2018.

NKK SWITCHES CO., LTD. <http://www.nkk.com> E-mail: nkkswitches@nkkswitches.co.jp

715-1 Unane, Takatsu-ku, Kawasaki-shi, 213-8553 Japan TEL: +81 44 813 8001 FAX: +81 44 813 8031